

OUT 69683

SECRET

- 2 -

(1) LEFT TEOC (S/N 64-15): MINOR LOW FREQUENCY BANDING IS PRESENT THROUGHOUT. TWENTY PERCENT OF MATERIAL WAS EXPOSED OVER WATER.

(2) RIGHT TEOC (S/N 64-20): MINOR LOW FREQUENCY BANDING THROUGHOUT.

C. ANALYSIS OF OOC:

(1) LEFT OOC (S/N 4019): OPERATED SATISFACTORILY.

(2) RIGHT OOC (S/N 4032): OPERATED SATISFACTORILY.

4. THE REPRODUCTIONS RECEIVED AT NPIC ARE SATISFACTORY; HOWEVER, OVERALL INTERPRETABILITY IS DIMINISHED BY TERRAIN CONDITIONS (NOTE PARA 3A) AND THE FACT THAT ONLY SINGLE LEVEL REPRODUCTIONS WERE

PAGE 4 RUEADJU 0036 S E C R E T
PRODUCED.

5. COMMENTS: A SLIGHT INCREASE IN EXPOSURE AND A SLIGHT DECREASE IN THE PRINTING LEVEL MIGHT HAVE ENHANCED SOME TARGET AREAS; HOWEVER, CONCERN EXPRESSED BY PHOTO INTERPRETERS CANNOT BE ATTRIBUTED TO ANY MAJOR PROBLEM. LACK OF TERRAIN COVERAGE, ATMOSPHERICS, AND SEASONAL CONDITIONS ARE THE APPARENT REASONS FOR THE INTERPRETERS CONCERN.

GP-1

S E C R E T

END OF MESSAGE

GRUP-ONE